

# Dendrobium Community Consultative Committee



15 December 2011





- Environment and Community Update, including piezometer results – Peter McMillan
- Operational Update Wayne Price
- Update regarding Dendrobium Area 3B SMP Gary Brassington
- General Business
- Christmas Dinner

**Dendrobium Area 3B:** 

Developing the Subsidence Management Plan





#### Illawarra Coal has commenced developing its Subsidence Management Plan for Dendrobium Area 3B

- Legislation
- Key dates
- Conditions for subsidence management
- Groundwater monitoring plan

### **Government approvals**



- 2001 EPBC and EP&A Approval
- 2008 EP&A Modification
- Area 3B SMP Application

#### **Target dates:**

- December 2011: Specialists reports due; AHIP process starts
- February 2012: SMP drafted
- March 2012: Draft SMP submitted

April 2012: Government review process commences



#### **Conditions 2, 3 & 5**

2. Ensure underground mining operations do not cause subsidence impacts at Sandy Creek and Wongawilli Creek other than minor impacts

3. Ensure development does not result in reduction in quality/quantity of surface water or groundwater inflows (Lake Cordeaux, Lake Avon, Cordeaux River at its confluence with Wongawilli Creek)

5. Ensure that subsidence does not cause erosion of the surface or changes in ecosystem functionality of Swamp 15a (structural integrity of controlling rockbar is maintained or restored)



# **Condition 7 – Subsidence Management Plan**

- integrate ongoing management of Dendrobium Areas 1 & 2, Watercourse & Swamp Impact monitoring, and Management & Contingency Plans (Conditions 4 & 6)
- include monitoring of subsidence effects
- SCA Assets Protection Plan
- monitoring, management and contingency plans for all other significant natural features and man made features (incl landscape, groundwater, flora/fauna/ecology, Aboriginal, utilities infrastructure)





# **Condition 8 – Subsidence Management Plan**

- include a mine plan
- detailed subsidence impact assessment
- minimum 2 years baseline data
- identify/assess significance of natural features within 600m of the edge of secondary extraction
- distinguish between, clearly describe and adequately quantify all subsidence effects, subsidence impacts and environmental consequences
- propose limits on subsidence impacts and environmental consequences to be applied within the relevant Area

# **Existing and proposed monitoring sites**









#### Groundwater monitoring plan (shallow auger holes)





### Groundwater monitoring plan (strata)



**bhp**billiton



# bhpbilliton resourcing the future

# Dendrobium Community Consultative Committee

Illawarra Coal presentation 16 February 2012







- Environment and Community Update, including piezometer results
- Dendrobium Operational Update
- Other operational updates
- General Business

# **Dendrobium Area 3B:**

# Update on developing the Subsidence Management Plan bhpbilliton resourcing the future



#### Illawarra Coal has commenced developing its Subsidence Management Plan for Dendrobium Area 3B

- SMP
- Proposed mine plan
- Natural features
- Man made features


#### Area 3B SMP



- 2001 EPBC and 2008 EP&A Approvals
- Area 3B SMP Application
  - Specialists reports
  - AHIP process
  - Draft SMP
- Monitoring, management and contingency plans
  - All significant natural features
  - Aboriginal heritage and culture
  - Infrastructure

#### Area 3B SMP







U:\2012\112-041-01 - TAS - Dendrobium Area 3B SMP\Report\Build\Dendrobium Area 3 - Environmental Management Structure R0.docx

14 February 2012

I \Projects\Dendrobium\Area 3\MSEC459 - Area 3B - Longwalls 9 to



#### **Mine Plan**










Fig. 5.13 Photographs of Donalds Castle Creek within the Extents of Swamp Den05






Fig. 5.23 Photographs of Typical Cliffs along Wongawilli Creek (Courtesy of IC)





Fig. 5.27 Photographs of Swamp Den05 (Valley Infill Swamp)

#### Man Made Features



#### **Man Made Features**





Fig. 6.1 Photographs of the Abandoned Railway Corridor and a Cutting

#### **Man Made Features**





Fig. 6.4 Photograph of a Typical Fire Trail (Courtesy of IC)

#### **Man Made Features**





Fig. 6.5 Photograph of Lake Avon (Courtesy of IC)



# bhpbilliton resourcing the future