

resourcing the future

Illawarra Coal Holdings Pty Ltd
BHP Billiton Illawarra Coal Regional Operations Centre
Level 3. Enterprise 1. Innovation Campus. Squires Way
North Wollongong NSW 2500 Australia
PO Box 514
Unanderra NSW 2526 Australia
Tel +61 2 4286 3000 Fax +61 2 4286 3600
bhpbilliton.com

Head Regional Operations Unit Environment Protection Authority PO Box 513 Wollongong, NSW, 2520

Attn: William Dove,

Dear William,

ENVIRONMENTAL PROTECTION LICENCE (EPL 2504): PRP21 and PRP22

As required by Condition U4 and U5 of Environmental Protection Licence 2504, please find below the outcomes of work undertaken to meet the requirements of Pollution Reduction Programs 21 and 22 respectively.

Pollution Reduction Program 21

This PRP required Endeavour Coal to implement the following 'best practice' dust control measures:

- Finalise and implement the Dust Forecast Ranking for predictive forecasting of adverse weather conditions;
- Retrofit water tankers so that a minimum of 2 tankers are available with a water cannon to spray stockpiles and coal loading areas during adverse weather conditions; and
- Continue the trial of haul road resurfacing with stabilising waste material including pulverised coal wash reject.

All of the above measures have been implemented, the details are provided in the table below.

Dust Control Measure	Implementation Details
Implementation of Dust Forecast Ranking System	Notification of adverse weather condition (trigger point: wind speeds > 40km/hr) are received by a number of personnel at the West Cliff site, listed below: — Environmental Superintendent; — Environmental Supervisor; — Emplacement Operations Manager (Contract Role); — Emplacement Operations Supervisor (Contract Role); — Emplacement Operations Leading Hand on-shift (Contract Role); and — Logistics Supervisor. The Emplacement Operations Manager (or delegate) reviews the notifications and assign sufficient resources (including deployment of up to two water carts) based on the forecast conditions. The process has been incorporated into the Daily Emplacement Inspection documents (Ref: 14-04-02C and 14-04-03C).
Retrofit two water tankers with water cannons	The site has two water carts fitted with water cannons. The deployment of the second watercart occurs if deemed appropriate following the assessment of the forecast weather conditions (as per process above). The water carts are managed through the Emplacement Contractor.
Haul Road Resurfacing	The following internal haul roads have been resurfaced with the stabilised waste material: — Front Road (ie. entry road to Stockpile 3; — Middle Road (ie. main haul road between Stockpile 1 and 2/3); and — Back Road (ie. main haul between Stockpile 3 and Road Receival). A plan showing the location of these roads is provided as Attachment 1.

Illawarra Coal Holdings Pty Ltd ABN 69 093 857 286

Pollution Reduction Program 22

This PRP required Endeavour Coal to undertake an investigation to:

- Quantify the amount of dust tracked out from the West Cliff site;
- Determine the effectiveness of the present dust control measures in reducing track out from the West Cliff site; and
- Identify further options to reduce the amount of coal dust that is tracked out on to Wedderburn and Appin Roads by trucks exiting the West Cliff site.

The investigation has been completed; please find enclosed a copy of the Investigation Report.

If you have any questions or would like to discuss further, please do not hesitate to contact me on (02) 4286 3394.

Yours Faithfully,

Scott Coleman

Manager Environment

Attachments:

Attachment 1: Haul Road Resurfacing Map

PRP22 Investigation Report

